

Elmendorf Aero Club

*P.O. Box 292
Elmendorf AFB, AK 99506-6001*

SPIF 10 - 01

Special Pilot Information File Information Carried Forward

1 January 2010

SPIF 10 – 01 is now in print for all members to review. This SPIF brings forward all information and prior PIF's from 2009 and earlier periods that will remain in place until they are placed into the 2010 Standard Operating Procedure (SOP) update.

Please review this PIF and the areas that it covers as well as the information it contains, please take note of all areas of concern with flight safety and club operations.

Examination of this information will improve your knowledge concerning your commitment to aviation safety and will help to improve the safety of Elmendorf Aero Club flying.

PIF 08 – 05	Cessna 182 Carburetor Icing
PIF 08 – 09	Hard Landings
PIF 07 – 11	Aircraft Inspections
PIF 09 – 03	Aircraft Engine Backfire & Carbon Monoxide Hazard
PIF 09 – 07	Elmendorf Aero Club Aircraft Run – Up Area
PIF 09 – 10	Winter Operations 2009 – 2010
PIF 09 – 11	Elmendorf Aero Club Winter Operations Parking Of Aircraft In The Hangar
PIF 09 – 12	Elmendorf Aero Club Winter Operations Deep Heavy Snow Procedures

This PIF is to be in effect until all data is added to the next update of the Elmendorf Aero Club Standard Operating Procedure (SOP) or until contained dated material has expired